

Cofe <u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)		
TAKAKAZU TANAKA ET AL.		:	Examiner: Janis L. Dote	
Appln. No.: 10/649,679		:	Group Art Unit: 1756	
Filed: August 28, 2003		:		
For:	ELECTROPHOTOGRAPHIC	:	Certificate	
	PHOTOSENSITIVE MEMBER, PROCESS CARTRIDGE AND	:	JUN 3 0 2006	
	ELECTROPHOTOGRAPHIC APPARATUS) :)	of Correction	
U.S. Patent No.: 6,994,941 B2)		
Issued:	February 7, 2006)	June 2, 2006	
Commiss P.O. Box	ioner for Patents 1450			

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-mentioned

patent:

COLUMN 1

Alexandria, VA 22313-1450

Line 20, "Form" should read --From--; and

Line 27, "member" should read --members--.

COLUMN 3

Line 3, "have" should read --has--.

COLUMN 55

Line 24, "higher" should read --more highly--.

COLUMN 56

Line 63, "dibenzpirene" should read --dibenzpyrene--.

COLUMN 62

Line 65, "dimethoxymehtane" should read --dimethoxymethane--.

COLUMN 63

Line 36, "scratch" should read --scratched--.

COLUMN 73

Table 1, "scratch images" should read --scratched images--.

COLUMN 83

Line 37, "of" should be deleted.

These errors appear to be relatively insignificant and, therefore, have not been included in the Certificate of Correction which has been filed separately. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200



In re Patent of:)	
		:	Examiner: Janis L. Dote
TAKAKAZU TANAKA ET AL.)	
		:	Group Art Unit: 1756
Appln. No.: 10/649,679)	
		:	
Filed: August 28, 2003)	
		:	
For:	ELECTROPHOTOGRAPHIC)	
	PHOTOSENSITIVE MEMBER,	:	
	PROCESS CARTRIDGE AND)	
	ELECTROPHOTOGRAPHIC	:	
	APPARATUS)	
		:	
U.S. Patent No.: 6,994,941 B2)	
		:	
Issued:	February 7, 2006)	June 2, 2006
Commissi	ionon fon Dotonto		

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"00-206721" should read --2000-206721--; and "01-133994" should read --2001-133994--.

ON COVER PAGE AT (56) OTHER PUBLICATIONS

After "Peter Strohreigl et al.,": "phrnylrmnrsminr)," should read --phenyleneamine),--.

COLUMN 17

CT-11,

"
$$CH_3 \qquad CH_3 \qquad CH_3$$

should read

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,994,941 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 2 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 3 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

CT-18,

"
$$CH_3$$
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C
 H_3C

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

CT-12,

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,994,941 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 43

CT-56,

$$H_3C$$
 CH_3
 F
 H_3C
 CH_3
 H_3C
 CH_3
 CH_3
 CH_3
 CH_3
 CH_3

should read

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,994,941 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 67

CT-17A, "-continued

' should read

-continued

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"00-206721" should read --2000-206721--; and "01-133994" should read --2001-133994--.

ON COVER PAGE AT (56) OTHER PUBLICATIONS

After "Peter Strohreigl et al.,": "phrnylrmnrsminr)," should read --phenyleneamine),--.

COLUMN 17

CT-11,

"
$$CH_3$$

$$H_3C$$

$$N$$

$$CH_3$$

$$C$$

should read

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,994,941 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 2 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 3 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

CT-18,

"
$$CH_3$$

$$H_3C$$

$$N$$

$$N$$

$$N$$

$$S$$
"

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

CT-12,

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 43

should read

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>US 6,994,941 B2</u>

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 67

CT-17A, "-continued

should read

continued

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,994,941 B2</u>